

all be
tion
3-1-28 N.

COPY.

Hamburg Report Nr. 18008

Lloyd's Register of Shipping.



Port H a m b u r g / K i e l

30th of March, 1928.

This is to Certify that I have

Surveyed the Steel twin sc. Vessel " HILDA KNUDSEN "

afloat and in dry-dock at Kiel for repairs to the damaged

bottom plating and framing sustained during launching at

Nakskow where the vessel is under construction xxxxxxxx

*and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report, stating that all repairs
recommended by me have been completed to my satisfaction, and
that I have Recommended that she be* eligible for

C l a s s ✱ 100 A1 Contemplated.

being fit to carry xxxx be towed to Nakskow for Completion. xxxxx

xx




P. Kien.

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."



Lloyd's Register
Foundation

002062-002070-0056

Tons. Vert. B.)—10m, 7.27.
203
95
664
426