

1

How Tenthredina

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Stat S.S. K/ANITE*Report *Ys*No. *41594***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/82.)

Nature of Survey

When due

❖ 100-A-1. (Stat)

1 Dk (pt Stat) Well Deck

Cell D/B f 103' 153t, FPT 39t, APT 3L


BK 74, 3BH, Cen, Pumps A & C, Q96' B11' F31'

Machy Off

M

H

12-1-22



© 2020

Lloyd's Register
Foundation

002062-002070-0149