

3m.7.28.

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Stl Tw Sc M.V. "ENERGIE" Report Liv No. 94350

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey 1st Entry When due Revised Rules

* 100 A-1. (Steel) carrying Petroleum in Bulk
1 ~~DE~~ (Stl) web frames.

A P T 22 t.

FK, 8 BH, Lloyds A+C.P.

P 47' F 22' Machy aft.
TRUNK IN WELL



002101-002108-0191

FLOORS, Depth and thickness at mid-line in
Holds

in way of