

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME *Steel S.S. "ALBERT E. WATTS"*Report *Pld*No. *4110***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey _____

When due _____


✠ 100 A.1. (Steel) Carrying petroleum in bulk
 2 Dks (Steel) & web frames. Longitudinal framing
 Cell DB & E & B 62' 200t, ITf 40' 588t, FPT 228t, APT. 72t
 FK 17 BH (13 to Upper Dk, 4 to 2nd Dk) ft Cen, A & P, P 134', B 36', F 40'.


 M. J. M.
 7.3.21

M. J. M.
 7.3.21

It is Concluded the both Strips of the Bridge Side plating are as
 approved but the Surveyors should be requested to State if this is so

C. O.
 14.3.21. See also 21-3-21



© 2020

Lloyd's Register
Foundation

002109-002118-0023