

## Lloyd's Register of Shipping.

(Report on Vessel No. \_\_\_\_\_)

Port \_\_\_\_\_)

To. SHIP ~~FORGINGS OR~~ CASTINGS.

We ~~XX~~ have to report that the undermentioned ~~XXXXXX~~ Steel ~~XXXXXXXXXX~~ Castings, manufactured by Messrs. Atlas-Werke A.G. of Bremen for the Vessel No. 155/156, being built by Messrs. Kockums Mek. Verkstedes A. Bof Malmö have been inspected by ~~us~~ <sup>us</sup> as set forth below and found to be, so far as can be seen, sound and free from defects.

Two rudder quadrant halves; one auxiliary quadrant.

Forgings or Castings.

Lloyd's

No. 184

M.10.3.28.

Bremen, 14th March, 1928.

G. H. C. Ham. Will. Mejer.

	1 rudder quadrant half	1 quadrant half	1 aux. quadrant.
	<del>XXXXXX</del>	<del>XXXXXX</del>	<del>XXXXXX</del>
	Annealed	Siemens - Martin	Steel
ide	cast	cast	cast
aled	yes	yes	yes
ons			
on Inspection	rough & finished	rough & finished	rough & finished
en Inspected	9/9/27. 10/11/27.	24/11/27. 13 & 31/1/28.	10/3.28.
ASTINGS.			
on Standard Test Pieces.			
Test—			
per square inch	27.1	28.1	26.45
sion per cent. ...	36 % in 2 ins.	36 % in 2 ins.	36 % in 2 ins.
nding Test—			
before fracture	120 degr. good	120 degr. good	120 degr. good
st—			
t from ground ...	14 feet	14 feet	14 feet
ring Test—			
de according to Rules	yes	yes	yes
found satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

e (if any chargeable) £

To be paid at Bremen.

f Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

002109-002118-0190

© 2020

Lloyd's Register  
Foundation