

Zapponia

F.E.

Receiver Surveyor *21. 4. 98*

Received from Chief Surveyor _____

VESS NAME *St. S. S. "Johanna"* Report *Guk* No. *11983*

Remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>3/20"</i>	<i>Proportions</i>
Spar Sheerstrake . .	<i>-</i>	<i>✓</i>
Description of Framing:— <i>ordinary</i> . (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100 A1 ("Steel") as recommended.

∇ 100 A1 ("Steel")

1 BR (pt. str. & pt. str.) & web frames.

N.B. = Cell D.B. a 56' u E 15' f 96' 253t FPT 35t APT 15t

FK. 4BH. Cem. LATCP.

C.H.J.
21/4/98

The Surveyors should be requested in future to write "Sheer Strake" to its corresponding letter in the table of plating in the first entry as the Committee particularly require this to be done.

BEAMS, F

"

"

PILLA

"

" Hold


" " *34.35*

" *46*

" Deck, Material and thickness *7. 1/2" x 1/2"*

" Deck Stringer Plating *1/2" x 1/2"*

002157-002164-0104



Lloyd's Register Foundation