

ived by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME "NERITOPSIS" REPORT Grk. 23417
Cls. No. 71171

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine Oil Engines 4 S.C.S.A.
8 Cy. 25 $\frac{7}{16}$ " - 55 $\frac{1}{8}$ "
754 MN

~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner Yes
If fitted with an outside gland of approved type No

The torsional vibration characteristics of this vessel's machinery have been examined in conjunction with the Firm's calculations and found satisfactory.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed LMC 10.46.

2 D.B. 180 lb.



© 2020
25. 11. 46.

Lloyd's Register
Foundation

002194-002205-0030