

[illegible][illegible]

GENERAL REMARKS—(continued).

PARTICULARS FOR RECORD in the REGISTER BOOK.—Length of Poop ☒ ft., R.Q.D. 67.8 ft., Bridge 8.78 ft., Forecastle 20.26 ft.
(in feet and tenths). When the Poop is joined to the B.D., this should be distinctly stated ☒

No. and Material of Decks (if Iron or Steel) and whether wholly or partially covered with wood, and No. of tiers of Beams (this information is to be given as it should appear in the Register Book) *10K*
Official No. *139306*; Signal Letters _____ State if Machinery is fitted aft *mach aft*
How are the surfaces preserved from oxidation? Inside *Cement & Paint* Outside *Paint*

PARTICULARS OF WATER BALLAST.—State whether the Double bottom is constructed on the cellular system or with girders on floors

Where Fitted.	*Length. Feet.	Water Capacity. Tons.	Where Fitted.	*Length. Feet.	Water Capacity. Tons.
Double bottom, aft,			Fore peak tank,	<input checked="" type="checkbox"/>	<i>38.76</i>
Double bottom, under Engines and Boilers,			After peak tank,	<input checked="" type="checkbox"/>	<i>1.78</i>
Double bottom, if under Engines only,			Deep tank, aft,		
Double bottom, if under Boilers only,			Deep tank, forward,		
Double bottom, forward,			Other tanks, if fitted,		
Total capacity of double bottom			(If necessary, furnish further information by sketch.)		

* The wells are not to be included in the lengths of the tanks.

State whether the above have been tested as required by the Rules *Yes*

Order for Special Survey No. *2687*
Date *27/4/16*
No. *723* in builder's yard.
DATES of Surveys held while building
1916: May 30 Jun 19. 23. 29 July 3. 10. 14. 17. 21. 27 Aug 1. 9. 18. 22. 25. Sep 13. 19. 27. Oct 4. 6. 18. 19. 20. 23. 25. 31. Nov 1. 2. 3. 7. 11. 20. 21. 24. 30. Dec 12

Surveyor's Signature

Matthew Blackwood

Total No. of Visits *36*