

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Steel S. S. "OUSEL"*

Report

Jul

No.

*17953*For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

When due

✱ 100-A-1. (Steel) Shelter Deck with foreboard

1 DK (Steel) v Shelter DK (Steel)

Cell DB 221' 369t, FPT 37t, APT 28t

FK, Collision BH to Shelter DK, ABH to upper DK, Cam, hlyds As CP.

F28 in Shelter DK



© 2020

2.2.22

Lloyd's Register
Foundation

002206-002214-0076