

Rpt. C 12(a)

Index No. _____
(For London Office only).

**FREEBOARD VERIFICATION FORM
FOR ORDINARY CARGO ^{AND}/_{OR} PASSENGER SHIPS.**

When received in London Office _____

Port _____
Name Itz do Sauró
Official No. _____ Signal Letters _____ No. in Reg. Book _____
Port of Registry Oponto Gross Tonnage 2323
Class _____ Date of Verification _____
Name of Owners _____

I have to report that the Freeboards as given below, assigned by the Committee to this ship, have been correctly marked on the ship's sides, in accordance with the printed instructions:—

	FREEBOARD AMIDSHIPS FROM TOP OF DECK LINE, <u>.076 m</u> WOOD/STEEL <u>on steel upper</u> DECK.		FROM CENTRE OF DISC.
Tropical Fresh Water	.710 m. ft.	ins.	.280 m ins. above
Fresh Water	.857 " ft.	ins.	.140 " ins. above
Tropical	.857 " ft.	ins.	.140 " ins. above
Summer	.997 " ft.	ins.	
Winter	1.137 " ft.	ins.	.140 " ins. below
Winter North Atlantic	1.187 " ft.	ins.	.190 " ins. below

Maximum Summer Draught Amidships corresponding to the freeboard assigned as shown on the Builders' Displacement Scales:— _____

Surveyor.

(To be filled up in London Office.)

Date of Committee's Minute 18:4:46

Particulars for Record in Register Book. {
Moulded Depth ft. ins.
Freeboard ft. ins.
Corresponding Draught ft. ins.

Freeboards compared and found correct by _____ Date 6-OCT-1947
Form for Certificate Portuguese

Certificate written 58 OCT 1947 Noted for posting