

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME St S S "KARTIGI" Rpt. Hpl No. 16323

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

^{1st Long}
 Transverse No. 5915 Depth "d" 11.7
 Framing: Table No. ' Description Bull angle frames as approved
^{2nd} Longitudinal No. 18257
 Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{\text{13.25}}{\text{}}$
 Deck Sheerstrake as approved.

Revised Rules

This vessel appears to have been built in accordance with the Revised Rules and the approved plans, and it is submitted she is eligible to be classed

✦ 100A.1. (Steel)

1 dk (Stl) " Cantilever framed topside tanks "

Cell D.B u E. B H6 f 186 60bt, Topside tanks 440t, F.P.T. 224t, APT 120t

F.K, 4 B.H, Lem, Lloyds A. CP.

P 81', F 29'. "machinery aft."

J.S.
5.8.25



© 2020

Lloyd's Register Foundation

002249-002259-0121