

nt to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Stal S. S. 'KENMARE'*Report *96*No. *41518***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

When due

Separate endorsement regarding date of build

* 100-A-1. (Stal) *"Shelter deck with foreboards"*

2 Dks (upt Stl) & Shelter Dk (pt Stl)

Cell DW a 67' U&Z 7' f 89' 213t, APT 12t

FK, 2BH to Shelter Dk, 3BH to upper Dk, Cen, Plyds A & C, B100 F45' on Shelter Dk

Date of build 11.21.

See letter 12.1.27
It is concluded the Workman's life is good but the Surveyors should be requested to state if this is so.

Wood
 00249-00289-0164

© 2020

 Lloyd's Register
 Foundation