

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME _____

S.C.K. "KINGSTON CHRYSOBERYL"

Rpt. _____

Hul _____

No. _____

45762

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. _____

2440

Depth "d" _____

2nd Long. No. _____

668

Proportions = $\frac{L}{D}$

10.49

Framing Bulb angle frames as approved

Sheerstrake _____

as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100A1 "Steam Trawler"

1 Dk

BK 8", 4 EH, Cem., Lloyd's A & CP

Q 86', F 29'

30

13.5.35



© 2020

Lloyd's Register
Foundation

002260-002268-0099

Spacing _____

20



© 2020
Lloyd's Register
Foundation