

"Machinist"

F.E.

Received by Chief Ship Surveyor 4. 1. 15

Received from Chief Ship Surveyor _____

VESSEL'S NAME A.C.S. ArklesideRpt. mdt No. 8780
Sea 26320

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 41. 2Depth "d" 11. 25Framing: Table No. 3 page 10 Description Butt angles as app^dLongitudinal No. 7432Proportions $\frac{\text{Length}}{\text{Depth}} =$ 13.3Upper Deck Sheerstrake as approved

The Underland Surveyors Report
that the survey has been completed

This vessel appears to have been built in accordance with the
Rules and the approved plans, and it is submitted she is eligible to
be classed ÷ 100 A.1. (Std) as recommended.

÷ 100 A.1 (Std)1 St (Im) Well StWB = (all DBf 136t. F.P.T. 33t. A.P.T. 28t.FK. 3 BH. (Im)Lloyd's A & B Q 119, B 11, F 12

© 2020
Lloyd's Register
Foundation
002289-002297-0059