

20012,10

1

Sent to Chief Surveyors

"MOUNT STEWART"

Received from Chief Surveyors

VESSEL'S NAME Steel SS. "SOMERSET COAST" Report G/S. No. 39805

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

The Downton Pump has been dispensed with for the present but it is concluded the Owners are agreeable to fit same when requested.

* 100 A. 1. (steel).

1 Dk (steel) 2" dk. (steel) in after hold. "Well Dk.

Cell DB of 159' 311 t. FRT 50t. APT 8t.

FK. 5 BH. Cern. Lloyd's AT.C.P.

P79', Q67', F28.

Machy. Aft.

© 2021

Lloyd's Register
Foundation

002298-002304-0007