

REPORT ON OIL ENGINE MACHINERY.

No. 58356

Received at London Office JUN 30 1937

Date of writing Report 19... When handed in at Local Office 3. 5. 1937 Port of Glasgow

No. in Survey held at Glasgow Date, First Survey 22. 3. 37 Last Survey 26. 4. 1937 Number of Visits 8

Reg. Book. on the Single Triple Quadruple Screw vessel "SAN CIPRIANO" Tons Gross 7966 Net 7767

Built at Glasgow By whom built Blythwood S B Co Ltd Yard No. 45 When built 1937

Engines made at Greenock By whom made J. G. Kincaid & Co Ltd Engine No K98 When made 1937

Donkey Boilers made at By whom made Boiler No. When made

Brake Horse Power Owners Eagle Oil & Shipping Co Ltd Port belonging to London

Nom. Horse Power as per Rule Is Refrigerating Machinery fitted for cargo purposes no Is Electric Light fitted yes

Trade for which vessel is intended carrying petroleum in bulk

II ENGINES, &c. Type of Engines 2 or 4 stroke cycle Single or double acting

Maximum pressure in cylinders Diameter of cylinders Length of stroke No. of cylinders No. of cranks

Mean Indicated Pressure Span of bearings, adjacent to the Crank, measured from inner edge to inner edge Is there a bearing between each crank

Revolutions per minute Flywheel dia. Weight Means of ignition Kind of fuel used

Crank Shaft, dia. of journals as per Rule as fitted Crank pin dia. Crank Webs Mid. length breadth Mid. length thickness Thickness parallel to axis shrunk Thickness around eyehole

Flywheel Shaft, diameter as per Rule as fitted Intermediate Shafts, diameter as per Rule as fitted Thrust Shaft, diameter at collars as per Rule as fitted

Tube Shaft, diameter as per Rule as fitted Screw Shaft, diameter as per Rule as fitted Is the tube screw shaft fitted with a continuous liner

Bronze Liners, thickness in way of bushes as per Rule as fitted Thickness between bushes as per rule as fitted Is the after end of the liner made watertight in the

propeller boss If the liner is in more than one length are the junctions made by fusion through the whole thickness of the liner

If the liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in water and non-corrosive

If two liners are fitted, is the shaft lapped or protected between the liners Is an approved Oil Gland or other appliance fitted at the after end of the tube

shaft If so, state type Length of Bearing in Stern Bush next to and supporting propeller

Propeller, dia. Pitch No. of blades Material whether Moveable Total Developed Surface sq. feet

Method of reversing Engines Is a governor or other arrangement fitted to prevent racing of the engine when declutched Means of lubrication

Thickness of cylinder liners Are the cylinders fitted with safety valves Are the exhaust pipes and silencers water cooled or lagged with

non-conducting material If the exhaust is led overboard near the waterline, what means are arranged to prevent water from being syphoned back to the engine

Cooling Water Pumps, No. Is the sea suction provided with an efficient strainer which can be cleared within the vessel

Bilge Pumps worked from the Main Engines, No. Diameter Stroke Can one be overhauled while the other is at work

Pumps connected to the Main Bilge Line No. and Size How driven

Is the cooling water led to the bilges If so, state what special arrangements are made to deal with this water in addition to the ordinary bilge pumping

arrangements Ballast Pumps, No. and size Power Driven Lubricating Oil Pumps, including Spare Pump, No. and size

Are two independent means arranged for circulating water through the Oil Cooler Suctions, connected to both Main Bilge Pumps and Auxiliary Bilge

Pumps, No. and size:—In Machinery Spaces In Pump Room

In Holds, &c. Independent Power Pump Direct Suctions to the Engine Room Bilges, No. and size

Are all the Bilge Suction pipes in Holds and Tunnel Well fitted with strum-boxes Are the Bilge Suctions in the Machinery Spaces

ed from easily accessible mud-boxes, placed above the level of the working floor, with straight tail pipes to the bilges

Are all Sea Connections fitted direct on the skin of the ship Are they fitted with Valves or Cocks

Are they fixed sufficiently high on the ship's side to be seen without lifting the platform plates Are the Overboard Discharges above or below the deep water line

Are they each fitted with a Discharge Valve always accessible on the plating of the vessel Are the Blow Off Cocks fitted with a spigot and brass covering plate

What pipes pass through the bunkers How are they protected

What pipes pass through the deep tanks Have they been tested as per Rule

Are all Pipes, Cocks, Valves, and Pumps in connection with the machinery and all boiler mountings accessible at all times

Is the arrangement of valves and their connections such as to prevent the possibility of water passing from the sea or from water tanks into the cargo or machinery spaces, or from one

compartment to another Is the Shaft Tunnel watertight Is it fitted with a watertight door worked from

of a wood vessel, what means are provided to prevent leakage of either fuel oil or of lubricating oil from saturating the woodwork


Main Air Compressors, No. No. of stages Diameters Stroke Driven by

Auxiliary Air Compressors, No. No. of stages Diameters Stroke Driven by

Small Auxiliary Air Compressors, No. No. of stages Diameters Stroke Driven by

Vacuuming Air Pumps, No. Diameter Stroke Driven by

Auxiliary Engines crank shafts, diameter as per Rule as fitted No. Position



AIR RECEIVERS:—Is each receiver, which can be isolated, fitted with a safety valve as per Rule.

Can the internal surfaces of the receivers be examined and cleaned

Is a drain fitted at the lowest part of each receiver

High Pressure Air Receivers, No.

Cubic capacity of each

Internal diameter

thickness

Seamless, lap welded or riveted longitudinal joint

Material

Range of tensile strength

Working pressure

by Rules

Actual

Starting Air Receivers, No.

Total cubic capacity

Internal diameter

thickness

Seamless, lap welded or riveted longitudinal joint

Material

Range of tensile strength

Working pressure

by Rules

Actual

IS A DONKEY BOILER FITTED?

If so, is a report now forwarded?

Is the donkey boiler intended to be used for domestic purposes only

PLANS. Are approved plans forwarded herewith for Shafting

(If not, state date of approval)

Receivers

Separate Fuel Tanks

Donkey Boilers

General Pumping Arrangements

Pumping Arrangements in Machinery Space

Oil Fuel Burning Arrangements

SPARE GEAR.

Has the spare gear required by the Rules been supplied

State the principal additional spare gear supplied

The foregoing is a correct description,

Manufacturer.

Dates of Survey while building	During progress of work in shops--	}				
	During erection on board vessel---	}	1937 Mar: 22. 25 Apr: 5. 13. 21. 22. 23. 26			
Total No. of visits			8			

Dates of Examination of principal parts—Cylinders Covers Pistons Rods Connecting rods

Crank shaft Flywheel shaft Thrust shaft Intermediate shafts Tube shaft

Screw shaft Propeller Stern tube Engine seatings 26-4-37 Engines holding down bolts

Completion of fitting sea connections 13-4-37 Completion of pumping arrangements Engines tried under working conditions

Crank shaft, Material Identification Mark Flywheel shaft, Material Identification Mark

Thrust shaft, Material Identification Mark Intermediate shafts, Material Identification Marks

Tube shaft, Material Identification Mark Screw shaft, Material Identification Mark

Is the flash point of the oil to be used over 150° F.

Have the requirements of the Rules for oil fuel pipes and tank fittings been complied with

Is the vessel (not being an oil tanker) fitted for carrying oil as cargo

If so, have the requirements of the Rules been complied with

If the notation for Ice Strengthening is desired, state whether the requirements in this respect have been complied with

Is this machinery duplicate of a previous case

If so, state name of vessel

General Remarks (State quality of workmanship, opinions as to class, &c.

BEFORE LAUNCHING

The stern tube, screw shaft and propeller fitted

The sea-cocks and valves fitted.

The engine seatings riveted and the rivet heads buffed flush

No bilge suction have been fitted.

The heating coils in the oil fuel double bottom tanks, the scalding tanks and the lubricating oil tanks have been tested to 250 lbs per sq hydraulic pressure.

The vessel has left for Greenock for the installation of machinery. Surveyors advised.

The amount of Entry Fee .. £	:	:	When applied for,
Special £	:	:	19.....
Donkey Boiler Fee ... £	:	:	When received,
Travelling Expenses (if any) £	:	:	19.....

S. C. Davis

Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute **GLASGOW 29 JUN 1937**

Assigned **SEE ACCOMPANYING MACHINERY REPORT.**



© 2020

Lloyd's Register Foundation