


"BONITA"


DJK 5851.
DJK 5862.

Before this case receives consideration,
the Djakarta Surveyor should confirm that he
satisfied himself that the Main and Auxiliary
machinery, including the pumping arrangements and
electrical equipment, were in good condition.
~~bearing in mind that statements from ship's personnel
should not be accepted.~~



9.6.61.

© 2020
002449-002456-0068



Lloyd's Register
Foundation