

C o p e n h a g e n

11th February 1920.


____ L. Klausen ____

the owners of the Steel Sc. Sr. "S r n e b o r g" of Copenhagen,
1908 Tons, on the 21st January 1920 hold a survey at this port
1144
on the cast steel safety valve chest of the starboard main boiler.

The safety valve chest was taken to the shop,
examined and found the casting somewhat spongy, mostly in way
of the walls separating the steam space from the space for the
springs.

Recommended the safety valve chest to be renewed within a period
of six months, say before the end of July 1920.

Sgd. L. Klausen.



© 2020

Lloyd's Register
Foundation

002477-002484-0134

2 frames in way bent and are do bend and cracked.
rarent and temporary repairs now done:-

18 Greenbury
Gpr. Rpt. No. 5803

J. R. KIMBURN

small 2. b. 2



© 2020
Lloyd's Register
Foundation