

William Doxford & Sons Ltd., Sunderland.

Yard No. 737

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Motor Tanker "BRITISH MARSHAL" REPORT Sld No. 34542

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 15795

Depth "d" -

2nd Long. No. 44413

Proportions = L 13.59
D

Framing As approved

Sheerstrake As approved

Sister vessel to "BRITISH MARQUIS"

Two longitudinal bulkheads are fitted.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ~~100A~~ "Carrying Petroleum in bulk".

1 Dk, 2nd dk in fore hold. "Longitudinal framing at bottom and at deck"
"Butts of keel plating elec. welded".

Cell DBuE 67' 37t, DTf 32' 383t, FPT 129t, APTs 165t.

FK, 17BH, Lloyd's A & CP


P 98' B 47' F 47'

Mchy Aft

O.L. 490.0'

E.S.D.

"at"



The Surveyors should be referred to the sister vessel "BRITISH MARQUIS" and again requested to report in future cases the lengths of the D.B. tanks as measured in accordance with Circular 1284.



© 2020

Lloyd's Register Foundation

002490-002491-0155

5.10.46

com.

f.e.d.