

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Stl. Sc. "BHADRAVATI"* Report *Glo* No. 52880**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1st Entry~~When due~~*Old Rules*

+ 100 A1 (Steel) Shelter D^K with freeboard,
1 D^K & Shelter D^K (Stl - Leaks).

bell DB u E 25' 50 t, FPT 55 t, APT 62 t.

FK. 5 BH (2 BH to Shelter D^K, 3 BH to Upper D^K). cem. Lloyd's A & CP.

F 34'



© 2020
15.9.32 *ffldw*

Lloyd's Register
Foundation

002498-002505-0313