

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME St. S. K "BRONTES" Rpt. Stul No. 44612

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

1st LONG
~~Transverse~~ No. 2271.5Depth "d" ✓Framing: Table No. ✓Description Angle frames as approved2nd Longitudinal No. 6198.5Proportions Length 10.44
Depth =~~Deck~~ Sheerstrake as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.1 (Steel) "Steam Trawler"


1 OK

APT_s. 14t FPT 9t

BK 8", 4BH, 6m, Lloyd's A & CP

Q85', F 26'

W. Butler Stevedoring



© 2020

Lloyd's Register
Foundation

002522-002528-0051

20.



© 2020

Lloyd's Register
Foundation