

Rpt. 9

Date of writing report 30/12/59.

Survey held at Hull.

Received London

No. of visits 1.

Port

HULL.

No. 65542.

First date

and

Last date 30/12/59.

REPORT OF PERIODICAL SURVEYS & REPAIRS OF MACHINERY

No. in R.B. 05091 Name S.S. "BRUNHAM" (Trawler).

Owners Henriksen & Co., Ltd.

Managers

Gross tons 425

Date of build 1934

Engines made Mdb.

By

Smith's Dock Co., Ltd.

Port of Registry Hull.

Type

Triple Expansion.

No. of Main Engines 1

No. of Screws 1

No. of Main Boilers

W.P. 225 lb.

No. of Aux./Donkey Boilers

W.P.

Surveyed Afloat or in Dry Dock Afloat.

Nature of Survey

Completion of M.B.S.

Was Damage Report issued?

No.

Int. Cert.?

Yes.

Last Report (For Head Office only)

65371 - Hull

Records of Survey & Special Notations as per Register Book

Hull	Machinery
10001 trawler 8,59	LMC 5,57
s.s. 5,57	MBS 5,58
	TSC (N) 5,57

The condition of any of the following items is to be described as "good" only when the part has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where it is considered that re-examination or repairs should be effected before the due date of the next Periodical Examination a distinguishing mark thus † should be inserted against the item and the circumstances and action recommended described fully under "defects and repairs". At part or complete Special Surveys those items which are not applicable to the ship should be cancelled with a black line; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

DOCKING Propellers

Wear Down of Stern Bushes

Oil Glands

Sea Connections

Fastenings

Has Screwshaft Tubeshaft been drawn?

Date of Examination

Has Shaft been changed?

Has Shaft now fitted been previously used?

Has Shaft now examined/fitted a continuous liner?

Approved oil gland?

MAIN ENGINES (Recip. Steam or I.C.)

PORT

STARBOARD

1 Cyls., Covers, Pistons & Rods

2 Valves & Gears

3 Connecting Rods, Top Ends & Guides

Side

Centre

4 Crankpins & Bearings

Side

Centre

5 Journals & Bearings

MAIN ENGINE DRIVEN AIR COMPRESSORS

6 Cyls., Covers, Pistons & Rods

7 Connecting Rods & Top Ends

8 Crankpins & Bearings

9 Journals & Bearings

10 Coolers & Safety Devices

MAIN ENGINE DRIVEN SCAVENGE PUMPS

11 Cyls., Covers, Pistons & Rods

12 Connecting Rods & Top Ends

13 Crankpins & Bearings

14 Journals & Bearings

15 Levers

16 SCAVENGE BLOWERS

17 SUPERCHARGERS

MAIN TURBINES

18 Casings, Rotors, Blading, Bearings & Thrusts

19 EXHAUST STEAM TURBINES (WITH RECIP. ENGINES)

20 STEAM COMPRESSORS

21 CLUTCHES & HYDRAULIC COUPLINGS

22 REDUCTION GEARING

23 THRUST BLOCKS, SHAFTS & BEARINGS

24 INTERMEDIATE SHAFTS & BEARINGS

25 HOLDING DOWN BOLTS & CHOCKS

26 CONDENSERS (MAIN & AUX.)

27 STEAM RE-HEATERS

28 DE-SUPERHEATERS

29 STOP & MANOEUVRING VALVES

30 MAIN ENGINE DRIVEN PUMPS

31 CRANKCASE DOORS & EXPLOSION RELIEF DEVICES

Have Main Engines been tested working and manoeuvring?

OPINION OF MACHINERY AND RECOMMENDATIONS

The Machinery of this vessel, so far as now seen, is eligible in my opinion to remain as classed with fresh record of MBS 10,59 as previously recommended.

Date of Committee

TUESDAY 19 JAN 1960

Decision

MBS 10,59

Noted
for
Header

40m, 4,57. T. (MADE AND PRINTED IN ENGLAND)

Engine Surveyor to Lloyd's Register of Shipping

002536-002542-0015

32 Essential Independent Pumps (Identify by position)
33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls
34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?
35 Fresh Water Coolers
36 Lub. Oil Coolers
37 Heaters (state service)
38 Independent Air Compressors, Coolers & Safety Devices
39 Air Receivers & Safety devices—Main
40 Auxiliary
41 Oil Fuel Tanks (Not forming part of hull structure)
42 Evaporators
43 Have Evaporator Safety Valves been tested under steam?
44 Steering Machinery
45 Windlass
46 Fire Extinguishing Arrangements

AUXILIARY ENGINES (Identify by position)

Table with 4 columns: PROPULSION, PORT, STARBOARD, ELECTRICAL EQUIPMENT, and AUXILIARY EQUIPMENT. Rows include Generators, Exciters, Air Coolers, Motors, Control Gear, Cables, etc., Insulation Resistance, Insulating Oil Test, Overspeed Governors, Magnetic Couplings, and Air Gap.

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)
MAIN
AUXILIARY, DONKEY or PRESS
Superheaters
Safety Valves
Mountings, Doors & Fastenings
Safety Valves Adjusted to { Sat. 225 lb/sq. inch. Spt. 225 lb/sq. inch.
Boiler Securing Arrangements
Main Economisers
Exhaust Gas Heated Economisers
Steam Heated Steam Generators
Steam Generator Safety Valves Adjusted to
Were Oil Burning System & Remote Controls examined working in accordance with Rules?
Forced Circulating Pumps
Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules?
Funnel

EXAMINATION & TESTING OF STEAM PIPES (State material)
Main
Auxiliary (over 3 in. bore)
Were Copper Pipes annealed?
Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

The Main Boiler Survey is now completed, and safety valves have now been adjusted under steam.

LEAVE THIS SPACE BLANK

Survey fees
Damage fee
Expenses
Date when A/c rendered