

ECHODALE

To enable the vessel to proceed from U.K. to Saint John N.B. the following machinery parts should be examined: -

Main Engine: -

No. 2. unit complete (last ex<sup>d</sup>. in 12/53)

Nos 5, 6 & 8 units were last exam<sup>d</sup> in 5/56 and at least one of these units should be examined.

Auxiliaries One main air receiver,  
50 KW dynamo engine.  
Lub. oil pump.  
Fire extinguishing arrangements.

Electrical equipment to be megger tested & all machinery & pumping arrangements tried under working conditions

Auxiliary Boiler Survey to be held  
23/11/60

Machinery Survey to be exam<sup>d</sup> & dealt with as proposed for the voyage.