

NAME Rhineland ex Schwan REPORT No. \_\_\_\_\_

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in hundredths of an inch.

AMIDSHIP.					FORWARD.				AFT.				REMARKS.		
Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.			Diminution if any.	
	Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.	Std.		Port.	Std.
35	34	34	01	01											
35	33	35	02	-											
43	42	42	01	01	39	39	39	-	-	35	35	35	-	-	
43	42	42	01	01	57	53	57	02	-	35	34	35	01	-	
39	39	38		01	57	53	56	04	01	35	35	35	-	-	
39	38	39	01	-	45	45	45	-	-	35	32	34	03	01	<i>Stakes aft Shell                      plating over 5                      Strakes partially                      renewed due                      to damage.                      Port side strakes                      3-4 Strakes.</i>
39	38	38	01	01	45	45	44	-	01	35	33	33	02	02	
39	38	38	01	01	48	42	47	06	01	-	-	-	-	-	
39	38	38	01	01	48	48	48	-	-	-	-	-	-	-	
39	39	39	01	01	48	-	-			-	-	-	-	-	

Drillings at ends to be made in the vicinity of the peak bulkheads.

002647-002652-0180

BOTTOM.

Wells, Angle, E or