

"70GDO" \*

F.E.

Received by Chief Ship Surveyor

EX

Received from Chief Ship Surveyor

VESSEL'S NAME

St. S. S. ROSLAGEN

Rpt. Got-

No. 6086A

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

63

Depth "d" 17.5

Framing: Table No.

✓

Description

Bulbangle as approved

Longitudinal No.

16677

Proportions

$$\frac{\text{Length}}{\text{Depth}} = 9.63$$

Bulbangle Deck Sheerstrake as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

 $\frac{1}{2}$  100 A-1 (steel)

1 dk (stb)

Cell D.B. 224' 50st A.P.T.H.T

FK. ABH. pt cem pt asph. A.T.C.P

P 24' B 67' F 28'

The Committee of Classification to  
"Cargo battens not  
The above notation to be  
in the Register Book.



© 2021

 Lloyd's Register  
Foundation  
3.6.11

002682-002689-0067