

Breadth 22.15.  
Depth 11.75.

~~Braught Moulded~~

Do. Long Bridge to top of keel

If surveyed while building, afloat, or

First Entry.

5c,7,28.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Rpt.

No.

15681

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long

Transverse No.

1466

Depth "d"

11.67

Framing: Table No.

Description

Angle frames as approved

Longitudinal No.

3996

Proportions

Length

Depth =

9.01

Deck Sheerstrake

as approved

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

1st 1st A.1. (Stub) Steam Trawler  
1st

Df 5' 12"

BK 7 1/2, 3 BH, C. m. Lays A & C 10

002682-002689-0094

Spacing