

## Lloyd's Register of Shipping.

(Report on Vessel No. 15845 Port Middlebro)No. FL317 SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned Iron <sup>&</sup> Steel Forgings or Castings, manufactured by Messrs T. S. Forster & Co Ltd of Sunderland for the Vessel No.         , being built by S.T. Kingston Torquaise of          have been inspected by me as set forth below and found to be, so far as can be seen. Sound

Mark on Forgings or Castings.

Lloyd's

No. 9060

JD 19.10.36

J Dale  
Sunderland  
19.10.36

	STERN FRAME.	RUDDER FRAME.	STEM.
Material* ...	Main part. Ingot steel, some suspicion Forged & built up		
How made ...	5 3/4 to 4 1/4 dia		
If annealed ...	Fagins & bracing		
Dimensions ...	19.10.36		
Progress on Inspection ...			
Date when Inspected ...			
CASTINGS.			
Tests on Standard Test Pieces.			
<u>Tensile Test—</u>			
Tons per square inch ...	30.6	31.2	
Extension per cent. ...	31.7	33.7	
<u>Cold Bending Test—</u>			
Angle before fracture ...	180°	180°	
<u>Drop Test—</u>			
Height from ground ...			
<u>Hammering Test—</u>			
If made according to Rules and found satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) £ 2 : 2 : 0

Applied for 19 OCT. 1936

To be paid at

SUNDERLAND.

\* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.



with cargo, anchors examined and found satisfactory.

© 2020

Lloyd's Register Foundation



*2000*  
*2000*

RECEIVED

RECEIVED

*2000*  
*2000*

*2000*  
*2000*

*2000*  
*2000*



of Donkey  
eam Power  
in Main Bo  
n Donkey  
ast Rep  
Particu  
of Rep  
of Rep  
ates being  
es and in  
damage ce  
offered hi  
the Survey  
the Survey  
his was not  
" what Part  
what spec  
urveyor to  
e latest da  
the Survey  
the Survey  
he Survey  
he Survey  
crew shat  
shaft now  
he shaft  
date of ex  
Engine 1  
Survey :  
Now  
Can