

ed by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SEL'S NAME

"HADA"

REPORT


Gto

No. 329a

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

This case is fully stated in endorsement dated 1.6.49.

Plans of Oil Gland fitted to screw shaft have now been received and the design is acceptable in this instance for the notation of "O.G.".

A reply is awaited regarding the  $6\frac{1}{2}$  K.W. electric generator.

IT IS SUBMITTED the Groningen Surveyor be informed ~~that~~ in reply to their letter of the 22.6.49 that the plans of Oil Gland are acceptable in this instance for the notation of "O.G." and two copies of the plan should be returned. (One copy retained).

They should also be informed their remarks regarding the air compressors are noted, and that a reply to question concerning  $6\frac{1}{2}$  K.W. electric generator is awaited.

} See Rot. Lr.  
19/7/49

Insert in Register Book Column 7. "O.G."

Ent

30.6.49.



© 2020

Lloyd's Register  
Foundation