

REPORT OF SURVEY ON SHIPS CLASSED FOR GREAT LAKES AND ASSOCIATED SERVICES

Date of writing Report 10-6-1959 When handed in at Local Office 19 Port of MONTREAL

No. in Reg. Book 61252 Survey held at Montreal Date, First Survey and Last Survey 25-5-19 59 (No. of Visits 1)

on the Steel S.S. "FRANK WILKINSON"

TONNAGE:— Built at Glasgow By whom Barclay, Curle & Co. Ltd. When 1929 - 5

GROSS 1940 Owners Scott Misener Steamships Limited.

UNDER DK Managers R. Scott Misener Port belonging to Montreal

NET 1160

Surveyed Afloat or in Dry Dock? Afloat Name of Dock

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report, No. 3582 Port TTD

REPAIRS, OR EXAMINATION AS PER RULE FOR

LAKE Annual SURVEY

NOTE: Surveyors must indicate clearly the items examined (a crow mark is not sufficient), the condition found and the repairs effected.

CHARACTER. + for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
ES* Great Lakes & River St.	MBS* 4,52
Lawrence service	M. 2,58
10,55	TS (CL) 9,57
Lake s.s. 10,55	SPS. 2,57
A.S. 4,58	

	ITEMS EXAMINED AND CONDITION FOUND, ETC.
Holds including bulkheads, inner bottom plating, etc.	Good
Bilges & ceiling.	-do-
Tween decks.	-
Deck & deck erections.	Good
Machinery Space.	-do-
Under Engines & Boilers.	-do-
Masts, Rigging & Outfit.	-do-
Windlass & Hawse Pipes.	-do-
Air & Sounding Pipes with closing appliances.	-do-
Pumps and Pumping arrangements outside machinery space.	-do-
Steering arrangements including gear.	-do-
W.T. Doors & Sluice valves.	-do-
Ventilator coamings with their closing appliances.	-do-
Hatchway coamings with their closing appliances.	-do-
Casings, companionways and their closing appliances.	-do-
Superstructure bulkheads with their closing appliances.	-do-
Guard rails & freeing ports.	-do-
Overboard discharges, also ash chutes & other shell openings.	-do-

	EXAMINED	TESTED	CONDITION
Peaks	Yes	-	Good
Side Tanks in hold.			
Deep Tanks			
Cargo Tanks			
Cofferdams			
Pump Rooms			
(Tankers)			

Has a Load Line Annual Survey been held?	No
Has a Grain Survey been held?	Yes
Has a Damage Survey been held?	No

General Observations, Opinion as to Class, Recommendation, Etc.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Annual Survey 4,54" or "to remain as classed and to have record of docking, 1,54 and the notation Lake S.S. 4,54.

This ship is eligible to remain as classed with record of ANNUAL SURVEY 5,59

Survey Fee U.S.S.A. \$ 66.00

Special Damage or Repair Fee (if any) \$ 4.00

Travelling Expenses \$ 5.00

Second Surveyor's Fee (if any) \$

Committee's Minute THURSDAY - 9 JUL 1959

Character Assigned AS 5.59 MBS 2.59

Fees applied for, JUN 12 1959

A. K. McDougall


Surveyor to Lloyd's Register of Shipping.

(A. K. McDOUGALL)



© 2020

Lloyd's Register Foundation



007125-00735-0236