

Im.12.15.

26.6.16

*J. Ingaro*



F.E.

Received by Chief Ship Surveyor

15.6.16

Received from Chief Ship Surveyor

7947

VESSEL'S NAME

*Sheels "Denpartk"*

Rpt.

*Lib-*

No. 14995

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

*62.45*

Depth "d"

*17.98*

Framing: Table No.

*3 page 11.*

Description

*Bulk angle as approved.*

Longitudinal No.

*17486.*

Proportions

Length =

*10.07*

Depth =

*Bridge Deck Sheerstrake as approved.*

*The Dundee Surveyor now reports the survey has been completed.*


This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\star$  100A-1 (Steel) as recommended.

$\star$  100A-1 (Steel).

- 15K (Steel).

*see DB a 70 u E 28' + 124' - 523L. FRT. 55L. APT. 46L.*

*FK. 4BH. can. Lared. P 21 B 68 F 29*



© 2020

Lloyd's Register Foundation

002770-002783-0042

*26.6.16*