

Did the Surveyor examine the Safety Valves of the Donkey Boilers? ..... To what pressure were they afterwards adjusted under steam? .....  
Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ..... Yes ..... and of the Donkey Boilers? .....

## MONTREAL OFFICE

Name:- "CITY OF MONTREAL"

Report No. Mt1. 12099

Nature of Survey:- Pt.BS

The following remains to complete the survey:- Safety valves to be adjusted under steam

NOTE:- This vessel laid up pending a decision whether she will be commissioned this Season.

Recommendations:-

The Vessel appears eligible to remain as classed ~~without~~ <sup>with</sup> fresh record of MBS 12,57 when the survey is complete.

Insert  in S.R.L.

May 2nd, 1958

General Observations, Opinion, and Recommendation:-

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, covering the machinery.)

58002807-0085

