

# Lloyd's Register of Shipping.

JAN 9 1939


2502

## REPORT ON ANNUAL LOAD LINE SURVEY.

Ship JOSEWYN ex WHITWOOD Official Number 143104 Port of Registry Swansea  
 Survey Sunderland Dates of Survey 30<sup>th</sup> December 1938  
7<sup>th</sup> January 1939 Date of last Load Line Survey 16<sup>th</sup> May 1938

### PARTICULARS OF SURVEY.

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
<b>DECK PLAYS, INCLUDING SMALL HATCHWAYS.</b>			
on freeboard deck.			
their stays and stiffeners...	Good		
...	Good		
...	✓		
afterwards...	Good except	2 to be removed	4 <sup>th</sup> Jan 1939
...	Good		
number per hatchway)	Good (2)		
battens	Good		
and their fittings	Good		
supply, including spares, adequate?)	Good (4)		
<b>superstructure decks, including raised decks.</b>			
their stays and stiffeners	Good		
...	Good		
...	✓		
...	Good except	1 to be removed	4 <sup>th</sup> Jan 1939
number per hatchway)	Good (2)		
battens	Good		
and their fittings	Good		
supply, including spares, adequate?)	Good (4)		
<b>superstructures not intact or not protected as I closing appliances.</b>			
...	Good		
...	✓		
afterwards...	✓		
...	Good		
number per hatchway)	✓		
and Battens	✓		
supply, including spares, adequate?)	✓		



© 2021  
 Lloyd's Register  
 Foundation



Items examined.	Condition in which found.	Repairs.
		Necessary.
VENTILATORS IN EXPOSED POSITIONS.		
4. To spaces below freeboard deck.		
Coamings, their supports and deck connections ... ..	Good	
Closing arrangements ... ..	Good	
5. To spaces below decks of superstructures which are intact or closed by Class I appliances.		
Coamings, their supports and deck connections ... ..	Good	
Closing arrangements ... ..	Good	
AIR PIPES.		
6. Exposed on freeboard and superstructure decks.		
Closing arrangements ... ..	Good	
7. Within partially enclosed superstructures.		
Closing arrangements ... ..		
MACHINERY CASINGS.		
8. Casing Top.		
Fiddle openings, their covers and fastenings ... ..	Good	
Skylights, their fastenings, covers and lashings ... ..	Good	
9. Exposed on freeboard and raised quarter decks.		
Doors and fastenings ... ..		
10. Exposed on superstructure decks other than raised quarter decks.		
Doors and fastenings ... ..	Good	
11. Within partially enclosed superstructures.		
Doors and fastenings ... ..		
12. FLUSH BUNKER SCUTTLES and chain attachments		
13. COMPANIONWAYS, including deckhouses enclosing ladderways.		
Doors, fastenings, covers ... ..	Good	

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
ING APPLIANCES FOR OPENINGS IN PERSTRUCTURE BULKHEADS.			
ble ... ..	Good		
fore end...	✓		
after end ... ..	✓		
... ..	✓		
FWAY, CARGO AND COALING PORTS.			
's side and superstructures ... ..	✓		
PERS AND SANITARY DISCHARGE PIPES.			
... ..	Good		
SCUTTLES AND DEADLIGHTS ... ..			
... ..	Good		
ED RAILS ... ..			
... ..	Good		
ECTION AND ACCESS TO CREW'S ARTERS.			
ays ... ..	✓		
LINES (fittings and material) ... ..			
... ..	Good		
ING PORTS			
... ..	Good		
on bars ... ..	Good		
ER, TANKER OR SPECIAL STEAMER AD LINES.			
or appliances ... ..	✓		
S NOT INCLUDED IN THE FOREGOING			
... ..	✓		
LINE MARKS ... ..			
... ..	Verified & found correct		



(a).  
43.

CASTLE  
RE  
Ship  
Survey

W  
BRANCH  
LOW  
TEL. ADD.  
EAST PA  
TEL. ADD.  
A  
FENWICK  
ILE CHAM  
BRIDGE S  
TELEGRA  
"BRANCH  
"BRANCH  
le Se

ear S  
py c  
rwan

(i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters maintained on the ship in as effective a condition as they were in when the certificate was issued; and

(ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

Law  
ny

R. B. 9/11/39  
 L. L. 4  
 Two

© 2021  
Lloyd's Register  
Foundation