

28 DEC 1933

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel Tw. Sc. "FORDSDALE" Rpt. Lon No. 99511

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey _____

The London Surveyors report this vessel placed in dry dock, bottom cleaned and coated and on account of damage through grounding and heavy weather, 1 shell plate and 8 fore peak tank semi-box beam lugs have been renewed, 2 shell plates and 3 frames repaired and minor repairs carried out.

A new fuel oil tank has been fitted in No.1 hold in accordance with approved plans.

It is submitted the vessel appears worthy to remain as classed with record of survey 11,33.

100A1
Shelter dk
with freeboard
11,33 Lon
Fitted for oil fuel etc.



© 2020

Lloyd's Register
Foundation

W. J. L. L.
21/12/33

002846-002852-0218.1 1/2