

(L).

(Received at London Office 23 JUN 1959)

No. 12705

REPORT OF SURVEY ON SHIPS CLASSED FOR GREAT LAKES AND ASSOCIATED SERVICES

Date of writing Report 4 - 6 - 19 59 When handed in at Local Office 19 Port of MONTREAL
No. in Reg. Book 67375 Survey held at Montreal Date, First Survey & Last Survey 28 - 4 - 19 59
(No. of Visits ONE)

on the Steel S.S. "KINMOUNT"
TONNAGE:- 1711 Built at Collingwood By whom Collingwood S.B. Co. Ltd. When 1923 5
GROSS 1711 Owners Canada Steamship Lines Limited
UNDER DK Managers
NET 1167 Port belonging to Montreal

Surveyed Afloat or in Dry Dock? afloat Name of Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report, No. 12014 Port MR

REPAIRS, OR EXAMINATION AS PER RULE FOR

LAKE ANNUAL SURVEY

NOTE: Surveyors must indicate clearly the items examined (a crow mark is not sufficient), the condition found and the repairs effected.

CHARACTER. + for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
BS* Great Lakes & River St. Lawrence service.	MBS* 4,55 BS M 2,58
9,57	TS(CL) 9,57
Lake S.S. 9,57	s.p.s. 3,53
A.S. 4,58	

WRECK
SECTION

No.

ITEMS EXAMINED AND CONDITION FOUND, ETC.

Holds including bulkheads, inner bottom plating, etc.	Good
Bilges & ceiling.	-do-
Tween decks.	-
Deck & deck erections.	Good
Machinery Space.	-do-
Under Engines & Boilers.	-do-
Masts, Rigging & Outfit.	-do-
Windlass & Hawse Pipes.	-do-
Air & Sounding Pipes with closing appliances.	-do-
Pumps and Pumping arrangements outside machinery space.	-do-
Steering arrangements including gear.	-do-
W.T. Doors & Sluice valves.	-do-
Ventilator coamings with their closing appliances.	-do-
Hatchway coamings with their closing appliances.	-do-
Casings, companionways and their closing appliances.	-do-
Superstructure bulkheads with their closing appliances.	-do-
Guard rails & freeing ports.	-do-
Overboard discharges, also ash chutes & other shell openings.	-do-

	EXAMINED	TESTED	CONDITION
Peaks	Yes	-	Good
Side Tanks in hold.			
Deep Tanks			
Cargo Tanks			
Cofferdams			
Pump Rooms			
	(Tankers)		
Has a Load Line Annual Survey been held?	Yes		
Has a Grain Survey been held?	Yes		
Has a Damage Survey been held?	No		

General Observations, Opinion as to Class, Recommendation, Etc.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Annual Survey 4,54" or "to remain as classed and to have record of docking, I,54 and the notation Lake S.S. 4,54.

This ship is eligible to remain as classed with record of ANNUAL SURVEY 4,59

Survey Fee \$ 36.00
Special Damage or Repair Fee (if any) \$ 4.00
Travelling Expenses \$ 5.00
Second Surveyor's Fee (if any) \$
Fees applied for, JUN - 5, 1959

Committee's Minute
Character Assigned
TUESDAY 30 JUN 1959
AS4,59
MBS4,59

A. K. McDougall
Surveyor to Lloyd's Register of Shipping.

(A. K. McDOUGALL)
© 2020
Lloyd's Register
Foundation

002858-002869-0304

Noted
for
Header