

3m.7.28.

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Stl. Se. GODFREY B. HOLT

Report Liv

No. 95751

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.


(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1st Entry

When due _____

Revised Rules.

*100 A. 1. (steel).
with freeboard
2 Dks (Stl - weather dk tank 5).
FK. GBH. Com.
Lloyds A & CP
P 15' B 126' F 32
Cell 2B 282' 6476. EPT 566. APT 206*



© 2020

Lloyd's Register Foundation
*William A.
8. 8. 89.*

002875-0096

in Register Book.