

Has the insulation been examined throughout the cargo chambers

Yes

Has it been tested for dryness

Yes


Engine No. 181352 Made by J. & E. Hall

For "PACUARE"

Lon Report No. R 7270

It is submitted that ~~a copy of~~ this Report be
forwarded to the Liv Surveyors for their
~~returned~~ guidance and for completion.

5m.1.53.



Date

5/5/54

© 2020

Lloyd's Register
Foundation

002870-002875-0277