

1 E

ved by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SEL'S NAME "EMPIRE TRINIDAD"

REPORT

Grk.
Gls.

No. 23195
70044

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine Oil Engines 4 S.C.S.A.
6 Cy. 29 $\frac{1}{8}$ " - 59 $\frac{1}{16}$ "

~~Boilers fitted with forced draught~~

Tail Shaft.	If fitted with a continuous liner	Yes
	If fitted with an outside gland of approved type	No

Torsiograph records proved satisfactory.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

LMC 12.45
2 D.B. 150 lbs.

11.1.46



© 2021

Lloyd's Register
Foundation

002907-002915-0159