

WRECK SECTION

(Received at London Office)

No. 3741

Rpt. 9

Date of writing report 21

ON SHIPS CLASSED FOR GREAT LAKES AND ASSOCIATED SERVICES

Survey held at Goderich

When handed in at Local Office 7-5-1959

Port of Toronto, Ontario

REPO 1-5-

Survey held at Goderich, Ontario

Date, First Survey 7-5-1959

and Last Survey 22-4-1959

(No. of Visits 1)

on the Steel S. S. "JOHN B. RICHARDS"

TONNAGE:—

Built at Gls.

By whom Napier & Miller

When 1925 - 4

GROSS 1743

Owners Upper Lakes & St. Lawrence Transportation Co., Ltd.

UNDER DK

Managers J. D. Leitch

Port belonging to Toronto

NET 1236

Surveyed Afloat or in Dry Dock? afloat Name of Dock -

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report, No. 12126 Port ML

REPAIRS, OR EXAMINATION AS PER RULE FOR

LAKE annual SURVEY

NOTE: Surveyors must indicate clearly the items examined (a crow mark is not sufficient), the condition found and the repairs effected.

CHARACTER. + for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
BS* Great Lakes & Limited Gulf of St. Service	MBS* ES 9/55
Lake SS	M 3/58
A.S.	CL 9/55
DS	SPS 1/58

	ITEMS EXAMINED AND CONDITION FOUND, ETC.
Holdings including bulkheads, inner bottom plating, etc.	Good
Bilges & ceiling.	-do-
Tween decks.	-do-
Deck & deck erections.	-do-
Machinery Space.	-do-
Under Engines & Boilers.	-do-
Masts, Rigging & Outfit.	-do-
Windlass & Hawse Pipes.	-do-
Air & Sounding Pipes with closing appliances.	-do-
Pumps and Pumping arrangements outside machinery space.	-do-
Steering arrangements including gear.	-do-
W.T. Doors & Sluice valves.	-do-
Ventilator coamings with their closing appliances.	-do-
Hatchway coamings with their closing appliances.	-do-
Casings, companionways and their closing appliances.	-do-
Superstructure bulkheads with their closing appliances.	-do-
Guard rails & freeing ports.	-do-
Overboard discharges, also ash chutes & other shell openings.	-do-

	EXAMINED	TESTED	CONDITION
Peaks	Yes	No	Good
Side Tanks in hold.			
Deep Tanks			
Cargo Tanks			
Cofferdams (Tankers)			
Pump Rooms			
Has a Load Line Annual Survey been held?	Yes		
Has a Grain Survey been held?	Yes		
Has a Damage Survey been held?	No		

General Observations, Opinion as to Class, Recommendation, Etc.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Annual Survey 4,54" or "to remain as classed and to have record of docking, 1,54 and the notation Lake S.S. 4,54.

This ship is eligible to remain as classed with record of ANNUAL SURVEY 4,59

Survey Fee \$36.00
 U.S.S.A. \$4.00
 Special Damage or Repair Fee (if any) \$
 Travelling Expenses \$15.00
 Second Surveyor's Fee (if any) \$
 Committee's Minute
 Character Assigned AS 4.59 subject
 MBS 4.59

Fees applied for, May 27, 1959

THURSDAY - 9 JUL 1959

[Signature]
 Surveyor to Lloyd's Register of Shipping.
 F.G.H. White

WEDNESDAY - 5 APR 1967

Noted for Header

"Laid up pending survey"



002929-002937-0144