

fees paid

Chief Surveyors _____

Received from Chief Surveyors _____

'S NAME Sc.M.V."DORCASTIA". Report Grk. No. 20610.

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Survey 1st Entry. When due _____

100A1 "Carrying petroleum in bulk"

1 Dk, 2nd Dk, clear of cargo tanks, Longitudinal framing at bottom and
at deck.


Cell.DBu 69', 162t, DTf 25' 281t, FPT 143t, APT 94t.

FK, 17BH, Lloyd's A & C.P.

P 90', B42', F 69'

Machy. aft.

O.L. 484'.



© 2020

This is a sister ship to the "DAVILA".

Lloyd's Register
Foundation

003056-003064 - 0099