

COPY.

Lloyd's Register of Shipping.

908 "Tolcasia"
Greenock Report No. 20610

Port GREENOCK.

9th May, 1938.

This is to Certify that

J. D. BOYLE

the undersigned Surveyor to this Society did at the request of Messrs. John G. Kincaid & Co., Ltd., Engineers, Greenock, survey during construction Two Steel Air Reservoirs intended for their Engine No. K.115 - Messrs. Lithgows Limited's Ship No. 908.

The scantlings are in accordance with the Rules for a working pressure of 350 lbs. per square inch.

The material has been tested by the Surveyors to this Society.


These Reservoirs were tested in the presence of the undersigned to a hydraulic pressure of 575 lbs. per square inch, and found tight at that pressure.

The working pressure should not exceed three hundred and fifty pounds per square inch.

MARK ON RESERVOIRS.

No. 2151.
LLOYD'S TEST 575 lbs.
per square inch.
W. P. 350 lbs.
per square inch.
6/5/38. J.D.B.

FEE:- £8.8.0.



Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."