

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Steel Screw Ketch "CAPE PALLISER" Rpt. Hul. No. 47282

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 2527 Depth "d" --

2nd Long. No. 7161 Proportions =  $\frac{L}{D}$  --

Framing Bulb angle frames as approved Sheerstrake As approved

This is a <sup>similar</sup> ~~vessel~~ ship to the "CAPE CHELYUSKIN"

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \*100A1 'Steam Trawler'

1 Dk.

BK  $7\frac{1}{2}$ ", 4 BH, Cem., Lloyd's A & CP.

Q 89', F 27'

*[Handwritten signatures and date]*  
23.10.36



© 2020

Lloyd's Register Foundation

003106-003115-0266

200

1871  
1872  
1873

of the ...  
...  
...

...

...



© 2020  
Lloyd's Register  
Foundation



...

...

...

...

...