

2/5/5
788

"Name"

Subject

Appendix (a)

Special
Approved

of present

Docking: Special
Repairs to the
Equipment - ve

certification

containing

NOT

XXXXXXXXXXXX

XXXXXXXXXXXX

08 11, 62
08 11, 62 With

IN S. R. L. 1962
(Rudder stock
Rudder mainplate)



© 2020

Lloyd's Register
Foundation

003116-003123-00465

RECIPROCATING STEAM ENGINE SURVEYS


10E

Name "CHRISTIAN S"

ES. due 9.61

	PORT	STARBOARD
H.P. Cylinder & Piston		
1st I.P. Cylinder & Piston		
2nd I.P. Cylinder & Piston		
L.P. Cylinder & Piston		
H.P. Valve		
1st I.P. Valve	11.61	
2nd I.P. Valve		
L.P. Valve		
Crossheads		
Crank Pins		
Crank Shaft Journals		
L.P. Turbines		
Reduction Gearing or Electric Generators or Steam Compressors		
Electric Propelling Motors		
Thrust Shafts		
Intermediate Shafts		
	MAIN	AUXILIARY
Condensers	4.62.	
Air Pumps	attached - 9.61	
Circulating Pumps	4.62.	
Feed Pumps	attached - 9.61	
Feed Heaters		
Feed Filters		
Bilge Pumps		
Ballast Pumps	11.61	
General Service Pumps		
Lubricating Oil Pumps		
Lubricating Oil Coolers		
Oil Fuel Transfer Pumps		
Hydraulic Pumps for W.T. Doors		
Pumping Arrangements	11.61 for GE	
Oil Fuel Installation		
Forced Draught Fans		
Evaporators	not used.	
Distillers		
Steam Pipes		
Bulkhead Stop Valves		
Regulating Valves		
De-Superheaters		
Re-Heaters		
Dynamo Steam Engines		
Auxiliary Oil Engines		
Air Receivers		
Electrical Equipment	Generators & Governors Switchboards & Fittings Cables & Insulation Resistance } 11.61	
Steering Engine	11.61	
Windlass	11.61	
Fire Extinguishing Arrangements	11.61	
Sea Connections	4.61	

*Remains completed 11.62
including all main engine.*



© 2020

Holding Down Bolts, &c.

main engine test 4.61

Lloyd's Register Foundation

0096 2/2