

the undersigned Surveyor to this Society did at the request of
the Salvage Association, London, attend at the South Plant of the

S. J. L. Luckenbach

Blt-3396.

Submitted, that before dealing with this
case the Surveyor should be requested to forward
the particulars of the new turbines on a
first-entry report-form.

See Cablegram.

SL
28/3/23

S.O. 1/4/23



© 2020

Lloyd's Register
Foundation

003124-003130-0170

combustion chambers, tubes, smoke boxes and uptakes were heavily