

Condition of Class

Tonnage Opening Fitted.

NAME OF VESSEL.. "ERNEBANK".....

Extract from Freeboard Verification of marking form received
from..... Belfast Surveyors dated.. 8.2.37.....

| | | |
|--|----------------|--|
| Moulded depth | 29 | ft. 10 ins. |
| Corresponding draught | 26 | ft. 5 ins. |
| Moulded depth as shewn on draught sheet | 29 | ft. 10 ins. |
| Tropical freeboard | 2 3 | ft. 5 0 ins. <i>24 3.37 km.</i> |
| Summer " | 3 | ft. 7 ins. |
| Winter " | 4 | ft. 1 1/2 ins. |
| Winter North Atlantic freeboard | - | ft. - ins. |
| Fresh water allowance | 6 3/4 | ins. |

Marked from ~~xxxx~~/steel upper deck.

Checked by *km*.....

Date 27.2.37.....



© 2020

Lloyd's Register
Foundation

003175-003180-0159