

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Steel Pc "THOMAS HOLT"* Report *Liv* No. *95885*


**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey *24 ENTRY*

When due

*Revised Rules.*



*+ 100A 1. (Steel) with freeboard.  
2 DKS (Stl - waiker dk leak S)  
FK 6 BH Lem*

*Lloyd's A+C.P.*

*Cell DB 282' 6445 FPT 565 APT 205  
P 15' B 126' F 32'*

*[Signature] WSH 5/9/29*

003175-003180-0178

© 2020

Lloyd's Register  
Foundation