

COPY

BELONGS TO
ROTTERDAM REPORT NO. 51389

LLOYD'S REGISTER OF SHIPPING



Port of Rotterdam.

Date 22nd March, 1961

This is to Certify that I have

Surveyed the s.s. "STAD SCHIEDAM", 6140 tons gross of Rotterdam whilst placed in drydock at this port on the 6th March, 1961 and subsequent dates for Damage Survey and Docking Survey. .

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, also that I will Recommend that she be continued as classed with fresh record of Docking 3-61, subject to sternframe at outer (E.W. 3-61) and previously) to be re-examined next drydocking. Indented shell plates G15 and H14 (p.s) in way of no.4 hold and indented bottom plates B4, D4, D5, D6 (s.s from forward) to be re-examined next drydocking.

Surveyor to Lloyd's Register.

A. Zur-Muhlen

KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BiS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	SS(P)	Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

„While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.”

(Cert. B.)

© 2020 Lloyd's Register Foundation
003208-003216-0162