

003223-003232-0081

2m, 12.34.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Stl & THE COUNTESS Report Stl No. 48510**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Comm's Report, 24/5/92.)

Nature of Survey 1st Entry When due Revised Revised


✠ 100 A. I. (Steel).

1 D^K (Stl) Well D^K

Cell D.B 123' 174t, F.P.T. 56t, A.P.T 22t.

F.K, 3 B.H, Cem, Lloyd's A.C.P.

Q 111', B 11', F 30'. Machinery aft.



© 2020

Lloyd's Register Foundation

It is concluded the thickness of the strake below the sheer strake in the well is as apposed but the Surveyors should be requested to state if this is so