

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME *Steel S.S. BEN REOCH*

Report

*Ho*No. *41596***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey _____

When due _____

Owners letter regarding bulkhead omission attached

❖ *100.A.1. (Steel)*

2 Dhs (Steel)

Cell Dk 363' 1050t, ITa 32' 960t, APT 32t

*FK, Intermediate BH in forward hold and intermediate three dk BH in after hold
dispensed with 5BH to Upper Dk, 1BH to 2nd Dk only, pt Conn, 14x12 A.C.F.*

P35' B128 F45

003233-003239-0067

© 2020

Lloyd's Register Foundation

28-12-21