

# REPORT of SURVEY for REPAIRS, &c.

State of writing Report 11-5 1925 When handed in at Local Office 19- Port of Rotterdam

No. in Survey held at Schiedam Date, First Survey and Last Survey 5-5 1925

eg. Book. "STAD VLAARDINGEN"

10786 on the Wood, Iron or Steel &c.

TONNAGE:- Built at Flensburg By whom Flensburger Schiffbau When 1925

GROSS Owners Halcyon Lijn Owners' Address Rotterdam

UNDER DE Managers Port belonging to Rotterdam

NET

Surveyed Afloat or in Dry Dock? Name of Dock Waterway Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet } Particulars of Classification (which must be inserted

total capacity tons. FPT tons; APT tons; MT feet tons. } precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.  
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

CHARACTER. 100 A 1.

for Special Survey. Date of last Survey and of Periodical Surveys.

Years Assigned and expired.

Machinery and Boiler Surveys (including date of N.B., if any).

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined  
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Survey of Condition.  
This vessel has been placed in drydock by the Owners to ascertain whether the vessel had sustained any damage.  
Bottom and Rudder have been carefully examined and found in good and undamaged condition.

Survey confined to the above, please see Hamburg Surveyors Trial Entry Report.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fair'd or Repaired ...								
Fair'd or Repaired in place ...								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or I.M. of Wood Vessels
Decks	State if Tanks now tested	Engine Room Skylights	(State if on Felt.)
aulking of Decks	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Coamings	Ceiling	Scuppers	Boats
Beams & Fastenings	Cement or Asphalt (State which.)	Cargo Hatchways	Masts, Yards, &c.
Outside Plating	Rudder	Hatches	Condition, how ascertained
Breasthooks	Steering gear and its connections	Planking of Wood Vessels	(State if wedges removed)
Transoms	Windlass	Caulking ditto	Sails
Frames	Have Pumps now been examined and found efficient?	Treenails ditto	Equipment letter
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Anchors, No. of
Longitudinals	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	„ length size
Floors		Ditto ditto at other places ditto	(on board)
Keelsons		Stringers, Clamps & Shells ditto	„ Rule length size
Stringers		Salting ditto	Hawser & Warps
Inner Bottom Plating		(State if examined.)	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—  
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—“to remain as now classed in the Register Book without fresh record of Survey,” “to remain as classed and to have record of survey, 1,24,” or “to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND15, &c.”

For the information of the Committee.

Survey Fee (per Section 29) £ no fee Fees applied for, 19

Special Damage or Repair Fee (if any) (per Sec. 29) £ : Received by me, 19

Travelling Expenses (if chargeable) £ charged: 19

Second Surveyor's Fee (if any) £

Committee's Minute 12 JUN 1925

Character Assigned 100 A 1 with freeboard

Surveyor to Lloyd's Register of Shipping.

003240-003244-0133