

17 FEB 1959

Rpt. 9

Date of writing report 28-1-59 Received London Port MONTREAL No. 12567
Survey held at Kingston No. of visits 3 First date 8-12-58 Last date 14-1-59

REPORT OF PERIODICAL SURVEYS & REPAIRS OF MACHINERY

No. in R.B. 67194 Name S.S. "KEYDON" Gross tons 1739 Date of build 1927 - 5
Owners La Verendrye Line Limited Managers Port of Registry Montreal
Engines made 1927 By Blair & Company (1926) Limited Type T 3 Cy.

No. of Main Engines 2 No. of Screws 1
No. of Main Boilers 2 SB W.P. 180 lb.
No. of Aux./Donkey Boilers - W.P. -
Surveyed Afloat or in Dry Dock Afloat
Nature of Survey M.B.S. & E.S.
Was Damage Report issued? No Int. Cert.? No
Last Report (For Head Office only)

Records of Survey & Special Notations as per Register Book

Table with 2 columns: Hull and Machinery. Rows include BS* Great Lakes & Gulf of St. Lawrence service, Lake S.S., and A.S. with corresponding MBS* and S.P.S. values.

The condition of any of the following items is to be described as "good" only when the part has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where it is considered that re-examination or repairs should be effected before the due date of the next Periodical Examination a distinguishing mark thus † should be inserted against the item and the circumstances and action recommended described fully under "defects and repairs". At part or complete Special Surveys those items which are not applicable to the ship should be cancelled with a black line; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

Has a Survey also been held on Ship? YES If so, is the Report sent now, or when will it be sent?

DOCKING Propellers Wear Down of Stern Bushes Oil Glands Sea Connections
Fastenings Has Screwshaft Tubeshaft been drawn? Date of Examination Has Shaft been changed?
Has Shaft now fitted been previously used? Has Shaft now examined/fitted a continuous liner? Approved oil gland?

MAIN ENGINES (Recip. Steam) ~~XXXX~~ ~~XXXX~~ ~~XXXX~~ ~~XXXX~~

1 Cyls., Covers, Pistons & Rods All Good
2 Valves & Gears All Good
3 Connecting Rods, Top Ends & Guides Side Centre
4 Crankpins & Bearings Side Centre
5 Journals & Bearings

MAIN ENGINE DRIVEN AIR COMPRESSORS

6 Cyls., Covers, Pistons & Rods
7 Connecting Rods & Top Ends
8 Crankpins & Bearings
9 Journals & Bearings
10 Coolers & Safety Devices

MAIN ENGINE DRIVEN SCAVENGE PUMPS

11 Cyls., Covers, Pistons & Rods
12 Connecting Rods & Top Ends
13 Crankpins & Bearings
14 Journals & Bearings
15 Levers

16 SCAVENGE BLOWERS

17 SUPERCHARGERS

MAIN TURBINES

18 Casings, Rotors, Blading, Bearings & Thrusts

19 EXHAUST STEAM TURBINES (WITH RECIP. ENGINES)

20 STEAM COMPRESSORS

21 CLUTCHES & HYDRAULIC COUPLINGS

22 REDUCTION GEARING

23 THRUST BLOCKS, SHAFTS & BEARINGS

24 INTERMEDIATE SHAFTS & BEARINGS

25 HOLDING DOWN BOLTS & CHOCKS

26 CONDENSERS (MAIN ~~XXXX~~) Good (Tested)

27 STEAM RE-HEATERS

28 DE-SUPERHEATERS

29 STOP & MANOEUVRING VALVES

30 MAIN ENGINE DRIVEN PUMPS Air Pump, Feed & Bilge Rams Good

31 CRANKCASE DOORS & EXPLOSION RELIEF DEVICES Have Main Engines been tested working and manoeuvring?

OPINION OF MACHINERY AND RECOMMENDATIONS The Machinery of this vessel is eligible in my opinion to remain as classed with record of M.B.S.(1,59) now and E.S.(with date) when survey is complete.

Date of Committee TUESDAY 24 FEB 1959 Decision MBS 158

Noted for Header

© 2020 A.K.M. Dougall Engineer Surveyor to Lloyd's Register of Shipping (A. K. McDOUGALL) Foundation

03275-00281-0155

If certificate is required state where to be sent.

- 32 Essential Independent Pumps (Identify by position)
- 33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls
- 34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?
- 35 Fresh Water Coolers 36 Lub. Oil Coolers 37 Heaters (state service)
- 38 Independent Air Compressors, Coolers & Safety Devices
- 39 Air Receivers & Safety devices—Main 40 Auxiliary
- 41 Oil Fuel Tanks (Not forming part of hull structure)
- 42 Evaporators 43 Have Evaporator Safety Valves been tested under steam?
- 44 Steering Machinery 45 Windlass 46 Fire Extinguishing Arrangements

AUXILIARY ENGINES (Identify by position).....
Starboard Steam Generator Engine.

PROPULSION	PORT	STARBOARD	ELECTRICAL EQUIPMENT	AUXILIARY EQUIPMENT
a Generators				l Generators & Governors
b Exciters				m Motors
c Air Coolers				n Switchboards & Fittings
d Motors				o Circuit Breakers
e Air Coolers				p Cables
f Control Gear, Cables, etc.				q Insulation Resistance
g Insulation Resistance				r Steering Gear Generators and Motors
h Insulating Oil Test				s Navigation Light Indicators
i Overspeed Governors				
j Magnetic Couplings				
k Air Gap				

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)

MAIN Port 8-12-58. Starboard 16-12-58. AUXILIARY, DONKEY or PRESS

Superheaters -

Safety Valves Good

Mountings, Doors & Fastenings Good

Safety Valves Adjusted to { Sat. 180 P.S.I.
 { Spt.

Boiler Securing Arrangements Good

Main Economisers Exhaust Gas Heated Economisers

Steam Heated Steam Generators Steam Generator Safety Valves Adjusted to

Were Oil Burning System & Remote Controls examined working in accordance with Rules? Forced Circulating Pumps

Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules? Funnel Good

EXAMINATION & TESTING OF STEAM PIPES (State material)

Main Auxiliary (over 3 in. bore)

Were Copper Pipes annealed? Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

LEAVE THIS SPACE BLANK

Survey fees ... 60⁰⁰

Damage fee ...

Expenses... JAN 29 1959

Date when A/c rendered



© 2020
 Lloyd's Register
 Foundation